

Rev 2

8-9-24

## Request For Purchase 8-7-24

### Oneida County B&G

#### **Location:**

Oneida County Office Building

800 Park Ave. Utica NY 13501

#### **Scope Of Service:**

Replace leaking Butterfly Valves and connections for 5" HWR & HWS  
on a qty of three 2014 Unilux - watertube boilers at the County Office Building.

Replace Butterfly shut off valves with Victaulic brand butterfly valves.

**Boiler #2 & #3:** Repair leaking connections. Replace gaskets on Front flange connections.

Replace rusted flanges and gaskets on rear flange connections. \* Rev 2

Replace two butterfly valves that turn the water off for each connection. Repair leaking  
Connections to circulation pumps.

**Boiler #1 :** Repair leaking connections. Replace gaskets on Front flange connections.

Replace rusted flanges and gaskets on rear flange connections.

Replace two butterfly valves that turn the water off for each connection.

All Boilers: Replace butterfly valves near boiler circulation pumps. (qty 3)

#### **Total Quantities:**

Butterfly valves : qty 9


Flange Gaskets : qty 9

Flange and Gaskets: qty 3

Repair leaking 6" connection above boilers. (See picture) \* Rev 2

#### **Insulate:**

Insulate all pipes, valves & connections that had insulation removed to repair, or had  
insulation removed because of leaks.



**Leaking 6" connection** (Rev 2 added pictures)



**Rear flanges to be replaced**



**Butterfly valve near circulation pump to be replaced:**



**Front Flange to replace gaskets:**






**Circulation pump motor flanges to replace gaskets:**



**Front Butterfly valve and Flange**



**Rear Butterfly Valves to Replace:**

